



How to demould a corner

– Balustrade mould

How to demould a corner – balustrade mould

Prior to use, thoroughly oil all wood surfaces that come in contact with mould. This includes inner core and inside of support carrier box. Vegetable oil or grease can be used. We suggest 2 coats, allowing first coat to dry before applying second coat




1. Mould and carrier ready for demould.



2. Turn mould & carrier upside down.



3. Remove inner core.



4. 4 . Lift off outer carrier.



5. With carrier in upright position, place mould and concrete upside down on carrier.



6. Push concrete out of mould using wooden plunger.



7. Concrete drops loose into carrier & mould can be removed.



8. Using carrier handles lift off to reveal concrete Balustrade Corner.



ARMCON
CERTAINTY: IN CONCRETE